



State of Illinois
ENVIRONMENTAL PROTECTION AGENCY
MEMORANDUM

DATE: September 29, 2010
TO: Division Files - Bureau of Land
FROM: Chris Cahnovsky – Collinsville Region
SUBJECT: 1198010003 – Madison County
Estate of Chemetco
FOS File

On September 17, 2010, Michelle Cozadd and I conducted an inspection at Chemetco, Inc. Present during this inspection were Eric Watt with the Estate of Chemetco and Mike Murray of AIS.

TANK HOUSE

Most of the large pieces of concrete have been removed from the Tank House for offsite disposal at Roxana Landfill. Per Mr. Murray AIS will use a screening devise that is currently on site to screen the concrete from the fines. I explained that the concrete and debris screened from the MBM would be considered general construction or demolition debris and most likely a hazardous waste.


FINES BUILDING

I then inspected the Fines Building. In this building I observed that some of the debris has been removed from the concrete piles. However, large pieces of concrete were still mixed with fines. The waste had been removed from the fines from the hallway area of the Tank House. This waste material was still in the Fines Building in a small pile.

CNC

cc: Regional Files
cc: Erin Rednour
cc: Michelle Kerr - USEPA


NOTE: THE F
MORE
IS AGI
SOUTH
MORE
TOTAL



Photos 1-11
9-17-10



DIGITAL PHOTOGRAPHS File Names: 1198010003 ~ 0972010-[Exp. #001-011].jp



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: Southwest
Photo by: Chris
Cahnovsky
Exposure #: 001
Comments: Tank
House, cells
removed



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 002
Comments: Concrete
rubble in Tank
House



DIGITAL PHOTOGRAPHS File Names: 1198010003 ~ 0972010-[Exp. #001-011].jp



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 003
Comments: Concrete
rubble in Tank
House



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 004
Comments: Concrete
rubble in Tank
House



DIGITAL PHOTOGRAPHS File Names: 1198010003 ~ 0972010-[Exp. #001-011].jp



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 005
Comments: Concrete
rubble in Tank
House



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: Southwest
Photo by: Chris
Cahnovsky
Exposure #: 006
Comments: loading of
concrete for landfill
disposal



DIGITAL PHOTOGRAPHS File Names: 1198010003 ~ 0972010-[Exp. #001-011].jp



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: Northwest
Photo by: Chris
Cahnovsky
Exposure #: 007
Comments: Lead liners



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: West
Photo by: Chris
Cahnovsky
Exposure #: 008
Comments: RCRA
waste from Tank
House



DIGITAL PHOTOGRAPHS File Names: 1198010003 ~ 0972010-[Exp. #001-011].jp




Date: 09/17/2010
Time: 10:00 – 10:45
Direction: Northwest
Photo by: Chris
Cahnovsky
Exposure #: 009
Comments: Concrete
rubble in Fines
Building



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: Northwest
Photo by: Chris
Cahnovsky
Exposure #: 010
Comments: Concrete
rubble in Fines
Building



DIGITAL PHOTOGRAPHS File Names: 1198010003 ~ 0972010-[Exp. #001-011].jp



Date: 09/17/2010
Time: 10:00 – 10:45
Direction: Northeast
Photo by: Chris
Cahnovsky
Exposure #: 011
Comments: trash
removed from MBM
pile.